Location ID	Date/Time	VOC (ppm)	LEL (%)	12S (ppm)	CO (ppm)	O2 (%)	Particulates (ug/m3)	Benzene (ppm)	Xylene (ppm)	Toluene (ppm)	Naptha (ppm)	Comment	Location Type	Agency
1-930	4/7/2019 0:10	(1-1)	0	C	)	20.9	18	0	(pp.	(P.P)	(PP)	Dirt road off Jacintoport blvd	Routine	EPA
1-931	4/7/2019 0:38		0	C	)	20.9	15.9	0				Near 777 Sheldon road and Ridlon street in parking lot of food mall	Routine	EPA
1-932	4/7/2019 1:41		0	C	)	20.9	22.3	0				At Andrews Catholic Church at 827 Sheldon road	Routine	EPA
1-933	4/7/2019 2:09		0	C	)	20.9	32	0				At Sam Houston Elementary School at 3939/4041 Sam Houston parkway	School	EPA
1-934	4/7/2019 2:26		0	C	)	20.9	16.4	0				At Cloverleaf Park Bacon Street and Hillsboro Street	Routine	EPA
1-935	4/7/2019 2:50		0	C	)	20.9	18.1	0				14914-14998 Market Street Road on side of road across from Budget Ready Mix	Routine	EPA
1-936	4/7/2019 3:05		0	C	)	20.9	12.8	0				Near 15188/15310 Market Street across from Coca-Cola vending	Routine	EPA
1-937	4/7/2019 4:21		0	C	)	20.9	17.6	0				15902 Market Street and corner of Dezavala Road	Routine	EPA
1-938	4/7/2019 4:50		0	C	)	20.9	11.9	0				Near 16616 market street at terrace park boat staging area	Routine	EPA
1-939	4/7/2019 5:04		0	C	)	20.9	12.4	0				17002 market street	Routine	EPA
1-940	4/7/2019 5:17		0	C	)	20.9	14.4	0				In front of WEB Fleeting 17512 market street	Routine	EPA
3-140	4/7/2019 9:00		0	C	0	20.9		0				Jacintoport Blvd West of BW-8	Routine	EPA
1-941	4/7/2019 9:02		0	0	)	20.9	8.8	0				1st street across from steel containers	Routine	EPA
3-141	4/7/2019 9:13		0	0	0	20.9	5.5	0				entrance to coastal cargo - peninsula st entrance	Routine	EPA
1-942	4/7/2019 9:22	1.	0	(	)	20.9	9.3	1				Market street at southwest shipyard L. P.	Routine	EPA
3-142	4/7/2019 9:30		0	(	0	20.9	5.5	0				Jacintoport Dock - Landside Entrance sw corner	Routine	EPA
3-143	4/7/2019 9:45		0	(	0	20.9		0				W end of Jacintoport Dock	Routine	EPA
1-943	4/7/2019 9:46		0		)	20.9	9.2	0				Dezavala elementary school	School	EPA
1-944	4/7/2019 10:00		0		)	20.9	10.5	0				Cedar Lane at East Freeway Road	Routine	EPA
3-144	4/7/2019 10:12		0		0	20.9	10.5	0				16642 Jacintoport Blvd	Routine	EPA
1-945	4/7/2019 10:13		0		)	20.9	12.1	0				Sheldon road at Ridlon Ave.	Routine	EPA
3-145	4/7/2019 10:29		0		) 0	20.9	12.1	0				Cemex Entrance gate landside	Routine	EPA
1-946	4/7/2019 10:40		0		)	20.9	12	0				Woodforest Blvd west of Beltway 8	Routine	EPA
3-146	4/7/2019 10:49		0		0	20.9	12	0				Kirby Island Marine entrance	Routine	EPA
1-947	4/7/2019 10:59		7 0		)	20.9	13.1	0				North Shore 9th Grade Campus	School	EPA
1-948	4/7/2019 10:39		0		)	20.9	12.1	0				San Jacinto North College Campus on Uvalde Rd	School	EPA
3-147	4/7/2019 11:13				0	20.9	12.1	0	1			south of underpass between bw-8 & i-10 insctn	Routine	EPA
1-949	4/7/2019 11:25		0		0	20.9	15.2	0				Dr. Gerald Cobb 6th Grade Campus on New Forest Parkway	Routine	EPA
1-949					)	20.9	15.2 16.3	0					School	EPA
	4/7/2019 11:40		0		0		10.5	0				Anthony Aguire Jr High on Wallisville Road		
3-148	4/7/2019 11:40		0		0	20.9		0				W access road of BW-8 N of Jacintoport Exit	Routine	EPA EPA
3-149	4/7/2019 11:49		0		) U	20.9	15.7	0				intsctn of Jacintoport and Sheldon	Routine	EPA
1-951	4/7/2019 11:58		0		)	20.9	15.7	0				Hamblen Elementary on Dell Dale Street	School	EPA
1-952	4/7/2019 14:12		0		0	20.9	3.8	0				West Brentwood street at RR crossing	Routine	
3-150	4/7/2019 14:17		0		0	20.9		0	1			Jacintoport blvd W of BW-8	Routine	EPA EPA
3-151	4/7/2019 14:32		0		0	20.9	2	0				3260 Penn City Road	Routine	
1-953	4/7/2019 14:33		0		0	20.9	3	0				Grassington Dr and Deercrest Dr	Routine	EPA
3-152	4/7/2019 14:47		0		0	20.9		0	1			15632 Jacintoport Blvd S side of Road 1201 S Sheldon	Routine	EPA
3-153	4/7/2019 14:54		0		0	20.9	2.0	0					Routine	EPA
1-954	4/7/2019 15:03		0		)	20.9	3.8	0				Cloverleaf elementary school on Barbara Mae street 411 S Sheldon Rd	School	EPA
3-154	4/7/2019 15:04		0		0	20.9		0					Routine	EPA
3-155	4/7/2019 15:17		0		0	20.9	0.2	0	1			Ramsey Community Center Bldg B	Routine	EPA
1-955	4/7/2019 15:38		0			20.9	8.2	0				E 13th street and old underwood drive	Routine	EPA
3-156	4/7/2019 15:39		0		0	20.9		0	1			Boasso America Entrance Gate	Routine	EPA
3-157	4/7/2019 15:50		0		0	20.9		0				K Solv 1007 Lakeside Dr	Routine	EPA
3-158	4/7/2019 15:59		0		0	20.9		0				16425 N Shore Drive	Routine	EPA
3-159	4/7/2019 16:11		0		0	20.9		0				pops trak-ta-lube	Routine	EPA
3-160	4/7/2019 16:38		) O		0	20.9	40.4	0				SAS 15636 Market St	Routine	EPA
1-956	4/7/2019 16:42		J 0		) 	20.9	10.4	0				Clinton Drive at Shell Gate 4	Routine	EPA
3-161	4/7/2019 16:50		0	-	0	20.9	40.1	0				SMC industries gate - 2260 Appelt	Routine	EPA
1-957	4/7/2019 16:55		) 0	-	) -	20.9	16.1	0	1			Fidelity Church of Christ, 140 Fidelity Street	Routine	EPA
3-162	4/7/2019 17:07		0	C	0	20.9	2.7	0				Stanley Parts 16123 Market St	Routine	EPA
1-958	4/7/2019 17:15		0	C	J	20.9	3.6	0				Clinton Drive at Sinclair Street	Routine	EPA
1-959	4/7/2019 17:25		0	C	J	20.9	2.5	0				Clinton Drive at Shell Gate 1	Routine	EPA
1-960	4/7/2019 20:43		0	C	J	20.9	8	0				At San Jacinto Elementary School on 1302 E. 13th street	School	EPA
1-961	4/7/2019 21:12		0	C	)	20.9	7.1	0				At deer park Junior High School 340-398 E. 9th street	School	EPA
1-962	4/7/2019 21:53		0	C	J	20.9	5.8	0				At JSC federal credit union on 2200 E. 13th street	Routine	EPA
1-963	4/7/2019 22:11		0	С	)	20.9	5.9	0	1			At deer park North High School 502 E. 2nd street	School	EPA
1-964	4/7/2019 22:26		0	C	)	20.9	6.1	0				Corner of W. 1st street and 102 Elm street	Routine	EPA
1-965	4/7/2019 22:53		0	C		20.9	6.4	0				822 E. Sam Houston pkwy	Routine	EPA
1-966	4/7/2019 23:12		0	C		20.9	6	0				In front of deer park high school South Campus 550-678 W. San Augustine street	School	EPA
1-967	4/7/2019 23:38		0	C	)	20.9	5.9	0				At deer park city hall at 15401 Greendale drive and E. San Augustine street	Routine	EPA